

# Assembly Instructions

Components:

---




**x1**



---


A level should be used to mark out the holes.



Max. weight: 5 kg



**1**



**2**

